





330 N. Ross St. Beaverton, Michigan 48612, USA
Ph: 989.435.7741 TF: 877.702.4142
sales@brown-machine.com

SERVICE BULLETIN
iALERT!



Obsolete Acroloop Model 8010 Board



Obsolete Acroloop Model 8000 Board

Attention Brown Thermoforming Customers: Acroloop Boards No Longer Available

Acroloop has discontinued the production of their Model 8000 and Model 8010 motion control boards for TCS computer control systems. There is no direct replacement from Acroloop or a third party. Acroloop is still able to service and repair the Model 8010 board. If unrepairable, there are no replacements. The Model 8000 board is unrepairable, and there are no replacements.

To avoid any production interruptions, we highly recommend that you take the following action immediately:

Contact our Kit Sales Department for a quote on a complete upgrade of your motion control system.

989.435.7741 x1208 or
mbartholomew@brown-machine.com